



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

**SB04-0003**

March 8, 2004

Page 1 of 1

### **Subject: REVISED KMD DIP SWITCH SETTINGS**

It has come to our attention that the original service manuals for the KMD series of ice makers may have included incorrect DIP switch settings. Please reference the following chart for the correct factory settings.

MODEL	DIP SWITCH NUMBER									
	1	2	3	4	5	6	7	8	9	10
KMD-700MAH	0	0	0	0	1	1	1	0	0	0
KMD-700MWH	1	0	0	0	1	1	1	0	0	0
KMD-700MRH	1	0	0	0	1	1	1	0	0	0
KMD-900MAH	0	0	0	0	1	1	1	0	0	0
KMD-900MWH	1	0	0	0	1	1	1	0	0	0
KMD-900MRH	0	0	0	0	1	1	1	0	0	0

0 = OFF

1 = ON