



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB18-0002

May 22, 2018

Page 1 of 1


Subject: CRM_48(-XX) Caster Rail Substitution of 3A6717G01, 3A6869-01 and 3A8734-01

The CRMR48 caster rail design has been changed. All previous versions are no longer available and will sub to the parts shown below.

To replace please order the following:

- 3A8956-01 Caster rail (Qty. 1)
- 3A8957-01 Rear caster bracket (Qty. 2)

See the diagram below for installation of the Rear caster brackets.



CRM_48(-xx)

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.