



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB22-0004

July 21, 2022

Page 1 of 1

Subject: 440916-01 Fan Motor Sub

The fan motor 440916-01 will begin subbing to 4A7228-01 as inventory levels are depleted. These two motors are the essentially the same except for the wiring connection.

In the event, the unit you are repairing has a different connector simply cut off the connector(s) and make connections as required, following standard repair procedures.

If you have question concerning this Service Bulletin, please contact the Technical Support department techsupport@hoshizaki.com or 1-800-233-1940.