

HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB93-0007

June 2, 1993

SUBJECT: DB DOOR INTERLOCK SWITCH

The front panel interlock switch located at the top panel bracket has been eliminated from the DB dispensers, as it is not required by UL. The spout safety interlock switch will remain as protection against access to the auger during dispensing.

The interlock switch has been eliminated beginning with the following serial numbers:

DB-130C	S/N C10416 ---->
DB-200C	C11916 ---->

DM/ss