



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB95-0004

August 17, 1995

SUBJECT: DB-130/200 PUSH BUTTON SWITCH REPLACEMENT

Due to reports of moisture damaging the DB push button switch, we have added a protective barrier covering the switch. The barrier is available and can be ordered as a separate part using part number 3A0415-01. As of August 1, 1995, the push button switch part number 435745-01 will sub to part number SA0002 which will include a barrier.

When replacing the push button switch it will be necessary to install the new barrier covering the switch. Please refer to the drawing for the correct position and location.

This change was made effective on the following serial numbers:

DB-130 S/N D11041L and after

DB-200 S/N D13116K and after

