



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB96-0005R

June 3, 1996

SUBJECT: Magnetic Contactor change

The magnetic contactor used on the KM-1600 and KM 2000 models has been changed on the assembly line due to a new domestic supplier. The original contactor, Hoshizaki service part number 438215-01 now subs to replacement assembly number HS-051. This assembly includes contactor number 4A0819A01, mounting bracket, screws, and instructions.

This change was effective on auxiliary codes as follows:

Model	Beginning with Aux. code
KM-1600MRE	F1
KM-1600MRE 3	F2
KM-1600SWE	F1
KM-1600SWE 3	F1
KM-1600SRE	F1
KM-1600SRE 3	F1
KM-2000SWE 3	F1
KM-2000SRE 3	F2

If contactor replacement is required on models with the auxiliary codes above, order the new contactor without mounting hardware, part number 4A0819A01.

F-2000 models will continue to use 438215-01 as the original contactor when assembled. They will also use HS-051 as a replacement part.