



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB06-0003

July 7, 2006

Page 1 of 1

Subject: Magnetic contactor 428393-01 terminal identification change.

The terminal markings on magnetic contactor 428393-01 have changed. The physical location of the terminals on the new contactor is the same as the current contactor, only the terminal labeling has changed. This change is part of the conversion to RoHS compliant materials (Reduction of Hazardous Substances a European governmental requirement).

This particular contactor has been used on many different models from the KM-1300 series and smaller. When making connections for a service replacement part, use the following terminals:

ORIGINAL	TO	FUTURE
11		13
12		14
15		31/33
16		32/34
A		A1
B		A2

