



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

**SB01-0003R3**

Issued: May 2, 2001  
Revised May 19, 2017  
Page 1 of 2

**Subject: DCM BEARINGS AND BEARING HOUSINGS**

**\*\*NOTE THIS BULLETIN SUPERSEDS PB91-0011 REV. MAY 30, 1996\*\***

| MODEL<br>NUMBER            | EXTRUDING<br>HEAD | REPLACEMENT<br>BEARING | LOWER<br>HOUSING | REPLACEMENT<br>BEARING |
|----------------------------|-------------------|------------------------|------------------|------------------------|
| DCM-231U                   | NLA               | NLA                    | 206013G03        | NLA                    |
| DCM-241U                   | NLA               | NLA                    | 206013G03        | NLA                    |
| DCM-240BAA                 | NLA               | NLA                    | 206013G03        | NLA                    |
| DCM-240BAB                 | NLA               | NLA                    | 206013G03        | NLA                    |
| DCM-240BAE                 | 327236G02         | NLA                    | 206013G03        | NLA                    |
| DCM-240BAF                 | 327236G02         | NLA                    | 206013G03        | NLA                    |
| DCM-270BAH (-OS)           | 327236G02         | NLA                    | 206013G03        | NLA                    |
|                            |                   |                        |                  |                        |
| DCM-451U                   | 314360G02         | SP88-7313              | 214938G01        | SP88-7314              |
| DCM-450BAA/BWA             | 314360G02         | SP88-7313              | 214938G01        | SP88-7314              |
| DCM-450BAB                 | 314360G02         | SP88-7313              | 214938G01        | SP88-7314              |
| DCM-450BWB                 | 314360G02         | SP88-7313              | 214938G01        | SP88-7314              |
| DCM-450B_E                 | 314360G03         | SP88-7313              | 214938G01        | SP88-7314              |
| (Serial numbers up to F0)  |                   |                        |                  |                        |
| DCM-450B_E                 | 216530G04         | SP88-7313              | 2A0947G01        | SP88-7314              |
| (Serial numbers F1 and up) |                   |                        |                  |                        |
| DCM-500B_F                 | 216530G04         | SP88-7313              | 2A0947G01        | SP88-7314              |
| DCM-500B_H (-OS)           | 216530G04         | SP88-7313              | 2A0947G01        | SP88-7314              |
|                            |                   |                        |                  |                        |
| DT-400BAH-OS               | 327141G01         | NLA                    | 206013G03        | SP88-7312              |
|                            |                   |                        |                  |                        |
| DCM-701U/WU                | NLA               | SP88-7316              | 315732G02        | SP88-7317              |
| DCM-700BAA/BAB             | NLA               | SP88-7316              | 315732G02        | SP88-7317              |
| DCM-700BWA/BWB             | NLA               | SP88-7316              | 315732G02        | SP88-7317              |
| DCM-700B_E                 | NLA               | SP88-7316              | 315732G02        | SP88-7317              |
| (Serial numbers up to F0)  |                   |                        |                  |                        |
| DCM-700B_E                 | 2A1594G01         | SP88-7316              | 315732G02        | SP88-7317              |
| (Serial numbers F1 and up) |                   |                        |                  |                        |
| DCM-750B_F                 | 2A1594G01         | SP88-7316              | 315732G02        | SP88-7317              |
| DCM-750B_H (-OS)           | 2A1594G01         | SP88-7316              | 315732G02        | SP88-7317              |

The replacement sleeve-bearing part numbers SP88-7311 and SP88-7312, for the 45mm diameter DCM & Flaker evaporators have been discontinued as a service replacement parts

Since these bearings are no longer available, you will need to order the appropriate extruding head or lower housing for your model. At this time, the smaller diameter sleeves are the only ones that are no longer available. Larger sleeve bearings will remain the same and are available for the repress program.

The models affected are DCM-240/270B, C-100B, C-101B, F-300/330/500B, FT-400B & F-450M.

If you have any questions concerning this change, please contact the Technical Support Department at [tech-support@hoshizaki.com](mailto:tech-support@hoshizaki.com) or 1-800-233-1940.