



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB01-0004R3

Issued May 2, 2001

Revised May 19 2017

Page 1 of 2

Subject: FLAKER BEARINGS AND BEARING HOUSINGS

****NOTE THIS BULLETIN SUPERSEDES PB91-0012, SB01-0004 and SB01-004R1**

MODEL NUMBER	EXTRUDING HEAD	REPLACEMENT BEARING	LOWER HOUSING	REPLACEMENT BEARING
C-100BAE-AD (-DS)	364141G01	NLA	206013G03	SP88-7312
F-250BAA	NLA	NLA	206013G03	SP88-7312
F-251B & U	NLA	NLA	206013G03	SP88-7312
F-250BAE	340077G01	NLA	206013G03	SP88-7312
F-300BAF	340077G01	NLA	206013G03	SP88-7312
F-330BAH	340077G01	NLA	206013G03	SP88-7312
F-330BAH-C	327141G01	NLA	206013G03	SP88-7312
F-440BAA	NLA	SP88-7313	214938G01	SP88-7314
F-441U	NLA	SP88-7313	214938G01	SP88-7314
F-450BAB/BWB	NLA	NLA	206013G03	SP88-7312
F-450BAE	340077G01	NLA	206013G03	SP88-7312
F-450MAF / MAH	340077G01	NLA	206013G03	SP88-7312
F-450MAF-C / MAH-C	327141G01	NLA	206013G03	SP88-7312
F-500BAF	340077G01	NLA	206013G03	SP88-7312
F-500BAF-C	327141G01	NLA	206013G03	SP88-7312
F-650M_B/M_E	3A2175G01	SP88-7313	214938G01	SP88-7314
F-650M_E-C	3A2176G01	SP88-7313	214938G01	SP88-7314
F-800M_F/M_H	3A2175G01	SP88-7313	2A0947G01	SP88-7314
F-800M_F-C / M_H-C	3A2176G01	SP88-7313	2A0947G01	SP88-7314
F-801M_H	3A2175G01	SP88-7313	2A1977G01	SP88-7314
F-801M_H-C	3A2176G01	SP88-7313	2A1977G01	SP88-7314
F-1000M_B	321027G01	SP88-7313	211461G01	SP88-7314
F-1000M_E & -50	343603G01	SP88-7313	211461G01	SP88-7314
F-1000M_E-C	NLA	SP88-7313	211461G01	SP88-7314
F-1000M_F	3A2175G01	SP88-7313	2A0947G01	SP88-7314
F-1000M_F/C & -22	3A2176G01	SP88-7313	2A0947G01	SP88-7314
F-1100/F-1101 ALL	208117G02	SP88-7316	315732G02	SP88-7317
F-1001M_F / M_H	3A2175G01	SP88-7313	2A1977G01	SP88-7314
F-1001M_F-C / M_H-C	3A2176G01	SP88-7313	2A1977G01	SP88-7314
F-1500M_H	216407G01	SP88-7316	206509G02	SP88-7317
F-1500M_H-C	2A1594G01	SP88-7316	206509G02	SP88-7317
F-2000M_B	216407G01	SP88-7316	206509G02	SP88-7317
F-2000M_E 1/3	216407G01	SP88-7316	206509G02	SP88-7317
F-2000M_F 1/3 / M_H 1/3	216407G01	SP88-7316	206509G02	SP88-7317
F-2000M_F-C 1/3 / M_H-C 1/3	2A1594G01	SP88-7316	206509G02	SP88-7317

The replacement sleeve-bearing part numbers SP88-7311 and SP88-7312, for the 45mm diameter DCM & Flaker evaporators have been discontinued as a service replacement parts

Since these bearings are no longer available, you will need to order the appropriate extruding head or lower housing for your model. At this time, the smaller diameter sleeves are the only ones that are no longer available. Larger sleeve bearings will remain the same and are available for the repress program.

The models affected are DCM-240/270B, C-100B, C-101B, F-300/330/500B, FT-400B & F-450M.

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.