



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB02-0004

May 17, 2002


Page 1 of 1

Subject: SD-450 STAND MOUNTING HOLE MODIFICATION

When installing a “later” model DCM-500B_F unit on an “earlier” model SD-450 it may be necessary to modify the mounting holes on the SD-450. This is due to a change in the leg hole spacing on the DCM series. In order for the DCM unit to mount properly you will need to extend the four 20mm mounting holes, on top of the SD-450 10mm or (Approx. 1/2”) to the outside edge of the stand. (See Fig. 1) This will allow alignment and installation of all 4 mounting bolts. To determine if your equipment falls within this category please refer to the chart below.

Model Number	“Earlier” Serial Numbers	“Later” Serial Numbers
DCM-500BAF	L03225J or Earlier	L03226K or Later
DCM-500BWF	L00704G or Earlier	M00705A or Later
SD-450	**M03945C or Earlier**	M03946D or Later

*****NOTE**:*** Only the SD-450s in this range are affected and then only when installing a “Later” model DCM-500B_F.



(Fig. 1)

If you have any questions concerning this modification please do not hesitate to contact the technical support department at 1-800-233-1940.