



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

**SB04-0002**

**March 1, 2004**


**Page 1 of 1**

### **Subject: AM-100 AND AM-150 SERIES DOOR GASKET INSTALLATION AND INSPECTION.**

When replacing the bin door gasket on the above models it is important to insure that the door gasket is installed properly. Magnetic strips are inside the gasket on three sides. The gasket must be installed with the magnet on the right, left and top of the door. The bottom of the door gasket has no gasket.

The position of this gasket should also be checked when ever responding to a call where the door falls open or is pushed open before the unit shuts down on the bin control.

If you have any question concerning this subject please call 1-800-233-1940.



AM-100 and AM 150 series door assembly