



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB04-0006

May 15 2004

Page 1 of 1

Subject: AM-50BAE SERIES WATER INLET AND DRAIN FITTING CHANGES

Beginning with the following model and serial numbers AM-50BAE P12632E and AM-50BAE-AD P10110E the drain connection and location of the brass water inlet fitting will change.

In previous models the brass **water inlet fitting** was included in the unit's accessory bag. Beginning with these serial numbers it will be installed on the unit prior to shipping. The connection size will continue to be 1/2" FPT.

The **drain connection** for these units will also be changed from the 5/8" I.D. rubber hose to a standard 1/2" FPT fitting.

Hoshizaki requires a minimum 1/2" ID drain line connection to the unit including a vented tee.

The Spec Sheet, Instruction Manual, etc. will be updated to reflect these changes. In the interim a notice will be attached to the door to alert the installer of the above installation changes.

If you have any questions concerning this change please contact Technical Support at 1-800-233-1940.

