



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

**SB07-0006**

**November 2, 2007**

**Page 1 of 1**

### **Subject: SINGLE SECTION FREEZER COMPRESSOR CHANGE**

Please be aware that the compressor has been changed on all versions of the single section freezers. This new compressor and start components are not interchangeable with the previous version so it is important to order the proper parts by serial number. The new part numbers are shown below along with starting serial numbers for this change

New Compressor info:		FH1-AAC	S62821C
		FH1-AAC-HD	S60182C
Drier	4A0924-01	FH1-SSB	S60846B
Contactors	4A1307-01	FH1-SSB-HD	S60190C
Start Cap	4A2134-02		
Compressor	4A3815-01	RFH2-SSB	S60112H
Start Relay/Contactors	4A3683-01	RFH2-SSB-HD	S60077D
		RFH3-SSB	S60026C
		RFH3-SSB-HD	S60022D

**If you have any questions regarding this information please contact the Technical Support Department at: 1-800-233-1940.**