



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB08-0001

May 13, 2008

Page 1 of 1

Subject: KML-631 WATER PUMP CHANGE

Beginning with the 2008 production the water pump for the KML-631 models has been changed to part number (2A4408-01). Part of this change includes an additional relay (4A1307-01) in the control box to supply power to the water pump. The sequence of operation has not been changed and this relay is energized by the red wire from the number 4 pin on the K1 board connector as with standard KM series units. This power is then distributed to the coil for the pump relay through the yellow wire from terminal 5 on the control switch.

See below for the wiring diagram showing the additional relay. If you have any questions concerning this change please contact the Technical Support department at 1-800-233-1940.

Additional Relay (4A1307-01)

