

HOSHIZAKI AMERICA, INC. SERVICE BULLETIN

SB10-0009

December 2, 2010 **Updated 10-17-11** Page 1 of 1

Subject: Bin Control Bracket Extensions

In some cases, it is necessary to extend the bin control down into the bin in order to prevent the bin from overfilling and to eliminate Ice bridging in the bin. This is especially critical for some Ice on Beverage applications. A drop down extension bracket has been developed for these applications and in some cases are provided with the unit in the accessory bag. The extensions drop the ice level about 3" allowing an air space to prevent ice from packing against the dispenser bottom. We have found this to be an effective measure to reduce ice bridging.

The following KM Modular units include extension # HS-0239. Instructions are included in the accessory bag.

Models		Serial
KM-320M	Started	VxxxxxG
KM-515M	Started	VxxxxxG
KM-600M	Started	VxxxxxG
KM-650M	Started	VxxxxxG

NOTE: the extension brackert is now installed as part of the Assembly and the assembly must be mounted at installation.

See Service Bulletin: SB11-0004 for details.

HS-0239

The KM-901M also needs an extension bracket for some bin applications. It is typically needed on larger bins only. These applications are rare however if needed, order extension bracket # HS-0246. Instructions are included with the kit.


Note: Since this extension is rarely needed, it is not included in the unit Accessory Bag.



The KMS-750/1401MLH and KMD- 850/901M units are designed for dispenser applications and typically need an extension bracket to keep ice from bridging and pressing up against the removable reservoir during dispenser agitation. Extension number HS-0207 is included in the accessory bag. Instructions

are in the installation manual provided with the unit, on page 17. KMS-850/1401 units starting with serial UxxxxxH KMD-850/901 units Starting with serial VxxxxxB

This extension can also be used on the DKM unit which may have ice bridging issues in low use applications.



HS-0207

If you have any questions regarding these extensions please contact Technical Support at 1-800-233-1940.