



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB12-0002R2

Issued April 16, 2012

Revised August 31, 2012


Page 1 of 1

SUBJECT: C-100B Reservoir

The reservoir assembly for the C-100BAE series Hoshizaki part number 4A4369-01 is no longer available from Hoshizaki service parts. Our inventory has been depleted and we can no longer purchase this part. An exact replacement part is available through McMaster Carr.

You will find the reservoir part on page 480 in the McMaster Carr catalog See link:
<http://www.mcmaster.com/#catalog/118/480/=h4tv7e>

The valve and reservoir assembly part number is #7973K48.



The same reservoir is used on C-100BAF series models up to serial number A1. In the past, part number 4A4369-01 subbed to kit HS-5011 however this kit is no longer available due to the unavailability of reservoir parts. A conversion kit (HS-5060) has been developed for the C-100BAF series with serial numbers up to A1. Serial numbers A2 and after used a different reservoir and water circuit. See the C-100BAF Parts Manual for part numbers used on series A2 and after.

*Note: The HS-5060 cannot be used on C-100BAE units. The C-100BAE must use the reservoir type shown above.

If a reservoir is needed for a warranty repair on a C-100BAE order the part on line and add it to the warranty claim form and include a copy of the purchase invoice. We will allow the cost of the part and regular UPS shipping cost along with the normal labor allowance under warranty as long as a copy of the invoice showing shipping cost is provided with the claim.

If you have any questions concerning this change please contact Hoshizaki technical support at 1-800-233-1940.