



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB13-0001

January 21, 2013

Page 1 of 1

Subject: FLAKER / DCM WATER VALVE CHANGE.

The manufacture of the Flaker/DCM Series water inlet valve was changed. As a result of this change the part numbers have changed from 4A0865-01 to 4A5309-01. The new valve has a different thread which required the water supply pipe to also change to add the new fitting nut. As long as the correct water valve is ordered by serial number, it will not be necessary to replace the water supply pipe.

The fitting nut is assembled onto pipe at factory and is not field replaceable. See the table below for the correct parts and serial number break. If your serial number is before the serial numbers below you should order water valve part number 4A0865-01.

MODEL NUMBER	SERIAL NUMBER	WATER VALVE NUMBER	WATER SUPPLY PIPE
F-300B_F (-C)	B____C and after	4A5309-01	341367G02
F-330B_H (-C)	B____C and after	4A5309-01	3A4298G02
F-450M_H (-C)	B____C and after	4A5309-01	4A0891G04
F-500B_F (-C)	A____M and after	4A5309-01	4A0891G02
F-801M_H (-C)	B____C and after	4A5309-01	4A0891G02
F-1001M_H (-C)	B____C and after	4A5309-01	4A0891G02
F-1500M_H (-C)	B____C and after	4A5309-01	4A0891G02
F-2000M_H (-C)	B____C and after	4A5309-01	4A0891G02
FS-1001M_H (-C)	B____C and after	4A5309-01	3A7478G01
FS-1022M_H (-C)	B____C and after	4A5309-01	4A4026G02
FS-1500M_H (-C)	B____C and after	4A5309-01	4A0891G02
FD-801M_H (-C)	B____C and after	4A5309-01	4A4026G02
FD-1001M_H (-C)	B____C and after	4A5309-01	4A4026G02
DCM-270BAH (OS)	B____C and after	4A5309-01	2A4181G02

*** DCM-270BAH (OS) IS THE ONLY DCM THAT HAS CHANGED TO DATE.
DCM-300, DCM-500, AND DCM 751 HAVE NOT CHANGED AT THIS TIME.

If you have any questions regarding this information please contact Technical Support at:
1-800-233-1940.