



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB13-0004

March 27, 2013

Page 1 of 1

SUBJECT: KM-2400SRF3 and KM-2400SRH3 COMPRESSOR CHANGE

Compressor part number 4A2043-01 for the KM-2400SRF3 and KM-2400SRH3 has been subbed to 4A4782-01. This should be a drop in replacement as these compressors have the same foot print and fitting connections. It is however recommended that DIP switches number 1 and 2 be moved to the “ON” position during the replacement.

Remember you should always change the drier any time the refrigeration system is open. The drier for this unit is part number 4A2663-01

If you have any questions concerning this change please contact Technical Support at 1-800-233-1940.