



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB13-0014

November 14, 2013

Page 1 of 1

SUBJECT: KMD-850 SERIES DIP SWITCH SETTING CHANGE

There has been a change to the DIP switch settings on the KMD-850M_H series units. This change takes effect on all new units built with the RST80C1E (3A6900-02) compressor. These units were produced starting with the serial numbers shown below.

KMD-850MAH	C12001H
KMD-850MWH	C20146L
KMD-850MRH	C10791H

In the event that a KMD-850M_H unit built prior to these serial numbers requires a compressor replacement, the original CS08KQE (4A4066-01) will be replaced by RST80C1E (HS-5115 compressor kit). In this case it will be necessary to adjust the DIP switches to the current settings

Current factory DIP switch settings with RST80C1E compressor

DIP Switch Number	1	2	3	4	5	6	7	8	9	10
ON/OFF	OFF	ON	OFF	ON	ON	ON	ON	OFF	OFF	OFF

Note: The S5 DIP switches should all remain in the OFF position

If you have any questions on this issue please contact Technical Support at Tech-support@hoshizaki.com or 1-800-233-1940