



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB14-0013

August 4, 2014

Page 1 of 1

Subject: 4A4730-02 AND 4A4732-02 REMOTE COMPRESSORS (50 CYCLE)

We have been informed by the vendor that these parts will no longer be available. The compressors that are changing were used in the KM2100SRH350 and KM1601SRH350 models and used an internal crank case heater.

These compressors are no longer manufactured with an internal heater. When replacing the compressor in a remote unit, it will be necessary to order both the compressor and the external crank case heater.

Model	Part Name	NLA Part #	Replacement Part Number
KM2100SRH350	Compressor	4A4730-02	4A4730-01
	Heater		4A5397-02
KM1601SRH350	Compressor	4A4732-02	4A4732-01
	Heater		4A5397-02

If you have any questions please contact Technical Support at Techsupport@hoshizaki.com or 1-800-233-1940.