



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

SB14-0014R1

Issued September 24, 2014

Revised October 3, 2014

Page 1 of 1


**Subject: COMPRESSOR KIT SA0141 NLA (4A1726-14 CS14K6E-PFV)**

The 4A1412-02 (CS14K6E-PFV) compressor that was included in the SA0141 will no longer be manufactured with an internal crankcase heater. Therefore this kit as well as some individual compressor part numbers will now sub to 4A1726-14. Proper start components and drier must be ordered separately. For units that were manufactured with an internal crankcase heater it will be necessary to order an external heater in the event of a compressor replacement. See the chart below for appropriate part numbers.

4A1412-01 will sub to 4A1726-14 as well; however these compressors were used on models where no crankcase heater was required.

4A1412-03 compressors are currently used in applications that require a crankcase heater and in some applications that do not. It is only necessary to order the external heater for remote units.

Part Number	Subs to Compressor	Start Cap	Run Cap	Starter	Crankcase Heater (Remote units only)
4A1412-01 4A1412-02 4A1412-03 SA0041 SA0141	4A1726-14	3A0076-01	3A2005-05	4A1107-09	4A5397-02



If you have any questions please contact Technical Support at [Techsupport@hoshizaki.com](mailto:Techsupport@hoshizaki.com) or 1-800-233-1940.