



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

SB14-0015

September 24, 2014

Page 1 of 1


**Subject: COMPRESSOR KIT SA0142 NLA (4A1726-15 CS10K6E)**

The 4A1539-02 (CS10K6E-PFV) compressor that was included in the SA0142 will no longer be manufactured with an internal crankcase heater. Therefore this kit as well as some individual compressor part numbers will now sub to 4A1539-03. Proper start components must be ordered separately. For units that were manufactured with an internal crankcase heater it will be necessary to order an external heater in the event of a compressor replacement. See the chart below for appropriate part numbers.

4A1539-01 will sub as well to 4A1539-03; however these compressors were used on models where no crankcase heater was required.

4A1539-03 compressors are currently used in applications that require a crankcase heater and in some applications that do not. It is only necessary to order the external heater for remote units.

| Part Number                                | Subs to Compressor | Start Cap | Run Cap   | Starter   | Crankcase Heater (Remote units only) |
|--|--------------------|-----------|-----------|-----------|--------------------------------------|
| 4A1539-01<br>4A1539-02<br>SA0042<br>SA0142 | 4A1539-03          | 3A0076-11 | 4A1631-02 | 434172-01 | 4A5397-02                            |



If you have any questions please contact Technical Support at [Techsupport@hoshizaki.com](mailto:Techsupport@hoshizaki.com) or 1-800-233-1940.