



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB15-0004

Issued: March 11, 2015

Page 1 of 1

SUBJECT: Obsoleted Fan 4R2813-01

Fan part number 4R2813-01 has been discontinued by the vendor and the part number is being obsoleted. We currently have a limited supply for service parts and for change over in production. The fan motor will substitute per the chart below when service parts are depleted. In some cases, the fan will sub to a direct replacement. In other cases a service replacement kit will be required as shown.

Substitute Chart for Fan 4R2813-01

Model	Subs to	Requirements to replace
Sushi cases HNC-120~210AA Serial Q1 & after.	P03371-01	Direct replacement
Professional upright reach-in models where used.	4A5343-01	Direct replacement
HUR40/68A(D), HPR46A	SP-5158 for 1 fan models	Shroud and fan retrofit
HUR96A(D), HUF40/68A(D), HPR72A(D)	SP-5159 for 2 fan models	Shroud and fan retrofit

If you have any questions please contact Technical Support at Techsupport@hoshizaki.com or 1-800-233-1940.