



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB17-0003

January 27, 2017

Page 1 of 1

Subject: F-330BAH-C, F-330BAJ-C and F-450MAJ-C, cubelet series fuse size change.

It has come to our attention that in certain environmental situations the 1-amp control voltage fuse (24VAC) may open during normal operation.

Effective November 2016 we have replaced the 1-amp fuse with a 3-amp fuse. The new fuse part number is 4A0893-03.

In the event you are working with a unit that has a blown 1-amp control voltage fuse, please investigate for any possible causes. If no problems are found, replace the 1- amp fuse with a 3-amp version. (Bussman model AGC-3 fast acting, Hoshizaki part number 4A0893-03 or equivalent).

See the list below for affected models:

F-330BAH-C	F-330BAJ-C	F-450MAJ-C
------------	------------	------------

Although the issue only surfaced on cubelet models, in certain conditions. The fuse size was changed across the flaker/cubelet series of the F-330 and F-450 models.

If you have any questions concerning this change please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.