



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB18-0005R2

Issued October 9, 2018

Revised April 5, 2024

Page 1 of 1


Subject: IM Series actuator spring change.

This bulletin supersedes SB18-0005 and reverses the spring substitution in that service bulletin. The actuator spring for the IM-200 and IM-500 will now be part number 4H3473-01. It will also be the sub for 481332M01.

Spring part numbers 4H0287-01 and 481332M01 will sub to 4H3473-01 as inventory is depleted.

All three springs are interchangeable.

Note: In the event that the springs need to be replaced they should always be replaced in pairs.



If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.