

HOSHIZAKI AMERICA, INC. SERVICE BULLETIN

SB19-0004 November 5, 2019 Page 1 of 1

Subject: 427253-01 Gearmotor protector (NLA)

The gear motor protector 427253-01 is no longer available from the manufacture. This protector was used in several models and in different configurations. For that reason, it is necessary to substitute model specific kits for this protector.

If a replacement protector is needed, please see the chart below for the correct substitute kit.

Model	Serial	Replacement kit
F-330BAH	All	SP-5509
F-330BAJ	G2 serials and earlier	
C-100BAE, C-100BAF, C-101BAH	All	SP-5510
C-80BAJ	H0 serials and earlier	
F-300BAF	ALL	
F-300BAJ	G2 serials and earlier	SP-5513
DCM-270BAH (-OS)	H2 serials and earlier	

If you have any questions concerning this change, please contact the Technical Support Department at <u>tech-support@hoshizaki.com</u> or 1-800-233-1940.