

## HOSHIZAKI AMERICA, INC. SERVICE BULLETIN

SB21-0001 February 3, 2021 Page 1 of 1

Subject: SA0144 Compressor kit will be NLA

When inventory levels are depleted the SA0144 compressor kit will no longer be available.

For future orders it will be necessary to order the individual components, as called out in the specific model's parts list. We will also be removing subs from our system that were previously directed to this kit.

Currently this kit includes the following part numbers that may all be ordered individual as needed.

| Description     | Part number | Quantity |
|-----------------|-------------|----------|
| Compressor      | 4A4376-02   | 1        |
| Start Capacitor | 3A0076-12   | 1        |
| Run Capacitor   | 3A2005-06   | 1        |
| Starter         | 4A1107-13   | 1        |
| Drier           | 4A2666-01   | 1        |

As always, we recommend the replacement of start components and drier anytime a compressor is replaced. Please see each model's individual parts list for correct part numbers.

If you have question concerning this Service Bulletin, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.