



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB21-0006R4

Issued November 19, 2021

Revised August 5, 2025

Page 1 of 3

Subject: Evaporator changes

Hoshizaki is updating obsolete evaporators kits to KM Edge kits. Other Evaporators maybe added.

Current part number	Subs to	New part number	Models
1A2322G01 1A3956G01 SP-5356		SP-5359	KML-631M_H KML-700M_J
104167G01 1A4051G01 106492G01 1A2357G01 SP-5360S		SP-5360	KM-515M_H KM-600M_F KM-650M_J KML-700MWH-M
104442G01 104442G03 1A4309G01 SP-5361S		SP-5361	KM-1200M_B/M_E KM-1300M_F/M_H KM-1340M_H/M_J KM-1601M_H/M_J
2A0717G01 2A3562G01 2A3526G01 2A8120G01 SP-5364		SP-5370	KML-250M_H KML-325M_H KML-350M_F/M_H KML-351M_H KML-400M_E KML-450M_F/M_H KML-451M_H DKM-500B_H/B_J KM-320MAH

SB21-0006R4

Issued November 19, 2021

Revised August 5, 2025

Page 2 of 3

Current part number	Subs to	New part number	Models
1A1832G01 2A5154G01 2A8516G01 2A6668G01 HS-0228		SP-5372	KMS-2000MLH/MLJ
2A6365G01 2A8529G01		SP-5373	KMS-830MLH/MLJ
104407G01 106396G01 106396G02 1A2351G01 2A7659G01 2A7965G01 SP-5355		SP-5574	KM-600MAH KM-630M_E/M_F/M_H KM-650MAH /-E KM-900M_F KM-900M_H KM-901M_H
1A4623G01 2A2781G01 2A2781G02 2A8520G01 SP-5362 SP-5365		SP-5583	KMD-700M_H KMD-850M_H KMD-860M_J KMD-900M_H KMD-901M_H/
2A4144G01 SP-5366 SP-5369		SP-5586	KMD-450M_H KMD-460M_H/M_J KMD-530M_H/M_J
2A6657G01 2A4531G01 SP-5367		SP-5589	KMS-1401MLJ
104696G03 HS-006 HS-007 HS-0208 HS-0209		SP-5591 Includes both Left & Right Banks	KM-1300S_F KM-1301S_H KM-1601S_H KM-1600S_F
1A6529A01 2A5033G01 2A7659G01 2A7965G01 HS-008 HS-5023 SP-5182 SP-5354		SP-5597 Includes both Left & Right Banks	KM-1900S_H3 KM-2000S_B/S_E KM-2000S_F/S_H KM-2100S_H/3 KM-2100S_J/3 KM-2400S_F KM-2400S_H KM-2500S_H/3

SP-5368			
---------	--	--	--

SB21-0006R4

Issued November 19, 2021

Revised August 5, 2025

Page 3 of 3

Current part number	Subs to	New part number	Models
1A3820G01 SP-5358S		SP-5358	KM-901M_J KM-1100M_H/M_J
1A0138G01 103444G02		SP-5598	KM-280MAE
2A8343G01 2A8347G01 SP-5645S		SP-5371 *Note: this is a 3- evaporator bank that fits either left or right side	KM-1900S_J3 KM-2200S_J3 KM-2600S_J3 KMH-2100S_J3
1A4119G01 1A4119G02 SP-5425S		SP-5425	KM-350M_J KM-520M_J KM-660M_J
SP-5644S		SP-5430 (Left) SP-5431 (Right) Note: These are 3- evaporator banks order appropriate side	KM-1301S_J KM-1601S_J
371296G01 373810G01		SP-5374	KM-260BAH
371399G01 374022G01		SP-5376	KM-201B_H
252014G01 258411G01 270883G01 2A9133G01		SP-5377	KM-151BAH
253985G01 258402G01		SP-5381	KM-101BAH
252007G01 258587G01		SP-5382	KM-61BAH

Note: Evaporators S-0533, S-0641, S-0428, 2A7635G01, 2A7635G02, 103444G02 and 103317G01 are single evaporator plates, that are used in multiple assemblies. Please see individual part manuals for correct assembly part numbers.

If you have question concerning this Service Bulletin, please contact the Technical Support department Warranty Department techsupport@hoshizaki.com or 1-800-233-1940.