

HOSHIZAKI AMERICA, INC. SERVICE BULLETIN

SB23-0001 May 8, 2022 Page 1 of 1

Subject: MAGNETIC CONTACTOR 426535-01 SUB

Magnetic contactor 426535-01 is no longer available. This part will now sub to two parts 461944-01 magnetic contactor and 462804-01 base.

If it is required to replace 426535-01 please order both sub parts.

If you have question concerning this Service Bulletin, please contact the Technical Support department techsupport@hoshizaki.com or 1-800-233-1940.