



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB24-0001

January 19, 2024

Page 1 of 1

Subject: Fan motor and Thermostat part number subs

The part numbers for the following service part kits will be changing. This is being done to move these kits into the standard service kit number format.

The contents of the kits will not change only the part numbers and are interchangeable with the previous kits.

This conversion will take place when current inventories of the new kit are depleted.

TB0031 subs to SP-5676

TB0041 subs to SP-5677

FM115A subs to SP-5674

FM116A subs to SP-5675

If you have question concerning this Service Bulletin, please contact the Technical Support department techsupport@hoshizaki.com or 1-800-233-1940.