



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

SB24-0003

March 18, 2024

Page 1 of 1

**Subject: DCM OptiServe sensor change.**

The DCM Optiserve sensors have been changed. These new sensor assemblies are common across all DCM models and improve performance with certain types of cups and lighting.

These sensors are drop-in replacements and do not require any equipment modifications.

Previous sensor part number	New sensor part number	Application
4A3753G01 4A3753G03	4A7246A01	Ice
4A3753G02 4A3753G04	4A7246A02	Water

If you have any questions concerning this change, please contact the Technical Support Department at [tech-support@hoshizaki.com](mailto:tech-support@hoshizaki.com) or 1-800-233-1940.