



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB25-0001

February 3, 2025

Page 1 of 1

Subject: Back bar controller substitution

The controller for earlier models of back bar units will be changing from a CAREL controller to a EVCO controller. When replacing a controller, it is recommended to also replace the thermistor/probe. See table below for part numbers.

See table below for sub information

Original Part number	Subs to	New controller part number	New probe/thermistor part number
12188093	Subs to	12259260	12259417
12188079	Subs	12307125	12259417
12188079	Alternate sub	12274405 (Includes probe/thermistor 12259417)	

Please see SB25-0003 for additional information on the installation of this new controller.

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.