



HOSHIZAKI AMERICA, INC

SERVICE BULLETIN

SB26-0006

June 12, 2026

Page 1 of 1

Subject: SA0139 NLA (4A1420-02 and 4A1726-12)

Please note that compressor kit SA0139 will be discontinued and made no longer available (NLA). For future service needs, please order the individual components that were previously included in this kit.

The information below should also be used for compressor part numbers 4A1420-02 and 4A1726-12

The individual replacement parts are listed below.

Part name	Part number
Compressor	4A1726-12
Start Capacitor	3A0076-12
Run Capacitor	3A2005-13
Start Relay	4A1107-09
Drier	4A2663-01 (Subs to 4A1338-01)

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.