



HOSHIZAKI AMERICA, INC

SERVICE BULLETIN

SB26-0007

August 18, 2026

Page 1 of 1

Subject: P00025-01 COMPRESSOR CHANGE

Due to a vendor change, compressor part number **P00025-01** will no longer be supplied with the start components.

These components must now be ordered separately when replacing the compressor. As a reminder, Hoshizaki recommends replacing the start components and the liquid line drier whenever a compressor is replaced to help ensure proper system performance and reliability.

The individual replacement part numbers are listed below.

Part name	Part number
Compressor	P00025-01
Capacitor	4Y1175-01
Overload	P00363-01
Start Relay	R900A0001
Drier	P00026-01

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.