

HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB93-0001

JANUARY 13, 1993

SUBJECT: NAMEPLATE REFRIGERANT CHARGE KM-630MWB

It has come to our attention that we have units in the field that are stamped with the incorrect refrigerant charge on the nameplate labels for the KM-630MWB unit.

The nameplate states:

Refrigerant R502 2 Lbs. 3 oz.

The correct refrigerant charge is:

1 Lb. 8 oz.

The effective serial number range is B11751 through B22215. Please check your inventory for KM-630MWB units with serial numbers within this range. If you have inventory in stock contact the Hoshizaki Care Department at 1-800-233-1940 with the model and serial number and we will send 2 new stickers to place over the top of the charge amount on the model nameplates.

There are 2 model nameplates on the unit; one on the rear panel top right corner and one inside the compressor compartment on the left wall.

If you are servicing the sealed refrigerant system be sure to recharge the unit with the correct charge (1 lb. 8 oz.). Also call and request the new charge stickers to correct the unit if it has not been corrected previously.

DM/ss