

# HOSHIZAKI AMERICA, INC.

# SERVICE BULLETIN

**SB96-0007**

**September 9, 1996**

**SUBJECT: Compressor Change**

The original compressor for the KM-800 & 1200 model units was a Copeland Number CRE4-0225 PFV Hoshizaki Part number 434918-01. This compressor is no longer available.

434918-01 now subs to Hoshizaki part number SA0006 which is a Copeland number CR28KF- PFV.

The mounting for the new compressor is the same as the original. The suction and discharge connections are the same size however, they are located differently ( see drawings below ). You will also find that the new replacement does not have a process port for low side access. It will be necessary to add a low side access tee to the suction line as you modify the tubing to fit the new compressor connections.

The new compressor requires a different start capacitor which is shipped with the SA0006. The electrical terminals are marked C, S, & R on both compressors. Be sure to double check the wiring against the wiring diagram before starting the new compressor.

