



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB97-0003

May 1, 1997

SUBJECT: F-1101ASU / S-0387 REMOTE CONDENSER FAN MOTOR.

This bulletin affects equipment produced prior to 1987. The original condenser fan motor, part number 2U0048-01, for the S-0387 remote condenser is no longer available from the manufacturer. This part now substitutes to assembly number SPKU2AA-1.

The original fan motor was a 230 volt component. A 120 volt motor is supplied in the replacement assembly along with a step down transformer and the additional parts needed to replace the original motor. Follow the instructions provided in the assembly when installing the new fan motor.

The new assembly includes the following:

Quantity	Description	Part #	Mfg. #
1	Fan blade	417068-01	FW-30PHL
1	Fan motor	2U0090-01	EP-TZ56(A)
1	Capacitor	431928-01	6 MFD
1	Transformer	2U0130-01	2U0130
1	Snap bushing	420470-01	SB-625-8
1	Wiring label	338894-01	
4	Screw	M4 x 8	T2 screw
6	Connector	7921-1102	CE-5
1	Black wire	500mm	18 AWG
1	Dark blue wire	500mm	18 AWG
1	Installation instructions		