



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN


SB09-0007

June 5, 2009


Page 1 of 1

Subject: WIRING CHANGE TO THE F-1500M_H

Starting in April 2009 Hoshizaki has changed the wiring location of the main control switch. The control switch was originally wired through the main power supply wires coming in the control box. The new location is on the dark blue wire going to the primary side of the control transformer. See wiring diagrams below. This change allows for standardized wiring across the flaker line.



Original Wiring



New Wiring

If you have any questions regarding this information please contact the Tech Supports department at: 1-800-233-1940.