



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB14-0006

March 10, 2014

Page 1 of 1

Subject: Flaker Cubelet Series Cutter Change

Starting from September 2013 the cutter head has been changed from 327145-01 to 427183G01, on the F-1001M_H-C series cubelet units. A change will also occur on F-801M_H-C models later in 2014 and on the FS-1001MLH-C and FS-1022MLH-C series units in May 2014. The original cutter on the FS-1001MLH-C and FS-1022MLH-C was 4A3443G02. The new F-1001M_J-C series units will use cutter 427183G01 from the beginning.

Model	Effective date	Starting serial number	Previous Part Number	New Part Number	Recommended Dispenser Kit
F-801M_H-C	Future	Pending	327145-01	427183G01	HS-5034
F-1001M_J-C	All	D serials	-	427183G01	HS-5034
F-1001MAH-C	9-1-13	C20827J	327145-01	427183G01	HS-5034
F-1001MRH-C	9-1-13	C22324J	327145-01	427183G01	HS-5034
F-1001MWH-C	9-1-13	C20929J	327145-01	427183G01	HS-5034
FS-1001MLH-C	5-1-14	Pending	4A3443G02	427183G01	Not needed
FS-1022MLH-C	5-1-14	Pending	4A3443G02	427183G01	Not needed

This change will give you a slightly longer, more consistent Cubelet on the F-801/1001M_H-C series units. Cubelet size will not be affected on the FS series units.

The HS-2110 kit will be discontinued. Cutter 427183G01 will be eliminated from the HS-5034 kit in the future and it will be universal for all cubelet/dispenser applications as recommended in the chart above.

For wiring information or any additional questions please contact Technical Support at tech-support@hoshizaki.com or 1-800-233-1940