



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB15-0012

December 23, 2015

Page 1 of 1

Subject: 2A0610-01 and 2A0610-04 part number and material change

Part numbers 2A0610-01 and 2A0610-04 will be changing to 1A3951-01 and 1A3951-02 respectively. These parts are a direct sub and are backwards compatible. This sub changes the material from ABS to stainless steel.

If you have any questions concerning this sub please contact Technical Support at tech-support@hoshizaki.com or 1-800-233-1940.