



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

SB16-0006

December 5, 2016

Page 1 of 1

### **Subject: F-1002MLJ and F-2001MLJ shipping with nitrogen holding charge**

In order to comply with the future SNAP regulations, the F-1002MLJ and F-2001MLJ low side units will be shipping with a nitrogen holding charge. This nitrogen holding charge must be vented before connecting the unit to the rack system. Detailed instructions for this process can be found in the instruction manual included with the units or online at: <http://plus.hoshizakiamerica.com/techsupport/tech.asp>.

The instruction manual also lists the proper Evaporator Pressure Regulator(EPR) settings for different refrigerants. If, you have any questions concerning this issue please contact Technical support at [Tech-support@hoshizaki.com](mailto:Tech-support@hoshizaki.com) or 1-800-233-1940.