



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB18-0001R2

Issued March 2 2018

Revised April 30, 2026

Page 1 of 1

Subject: Individually packaged door kits for the C-80, C-101 and AM-50 series

Hoshizaki service parts has introduced the following individually boxed door assemblies for the C-80, C-101, and AM-50 series units. These assemblies include handles, labels, and door gaskets.

Beginning in 2024 there were construction changes to the door assemblies. These include new magnetic gaskets and interior panels. The revised kits also include new hinges which should be replaced when installing the new door.

See the chart below for the new assembly numbers that will be implemented, as stock of the original assemblies are depleted.

Model	Description	Originally assembly part number	New assembly part number
AM-50BAE	AM-50BAE Door Assembly	SP-5331	SP-5704
AM-50BAE-AD	AM-50BAE-AD Door Assembly	SP-5332	SP-5705
AM-50BAE-ADDS/AM-50BAJ-ADDS	AM-50BAE-ADDS/ AM-50BAJ-ADDS Door Assembly	SP-5333	SP-5706
AM-50BAE-DS/AM-50BAJ-DS	AM-50BAE-DS/ AM-50BAJ-DS Door Assembly	SP-5334	SP-5707
C-100BAF/C-101BAH	C-101BAH Door Assembly	SP-5335	SP-5700
C-100BAE-AD/C-100BAF-AD/C-101BAH-AD	C-101BAH-AD Door Assembly	SP-5336	SP-5701
C-100BAF-DS/C-101BAH-DS/C-80BAJ-DS	C-101BAH-DS/ C-80BAJ-DS Door Assembly	SP-5337	SP-5703
C-100BAE-ADDS/C-100BAF-ADDS/C-101BAH-ADDS/C-80BAJ-ADDS	C-101BAH-ADDS/C-80BAJ-ADDS Door Assembly	SP-5338	SP-5702
AM-50BAJ	AM-50BAJ Door Assembly	SP-5339	SP-5704
AM-50BAJ-AD	AM-50BAJ-AD Door Assembly	SP-5340	SP-5705
C-80BAJ	C-80BAJ Door Assembly	SP-5341	SP-5700
C-80BAJ-AD	C-80BAJ-AD Door Assembly	SP-5342	SP-5701

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.