



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB20-0008

April 14, 2020

Page 1 of 1

Subject: Steelheart undercounter refrigeration component part numbers

If replacing the cap tube or heat exchanger on the Steelheart undercounter series, please reference the information below. These units were manufactured beginning in late 2018 and use R-290 refrigerant

Note: Must replace heat exchanger with condensing unit.

Model Number	Condensing unit (Includes drier)	Cap-tube kit	Drier	Serial number
UR27 - WR27	3A9520- 01	SP-5437	2A9121- 01	G5 to K5
SR27	3A9316- 01	SP-5437	2A9121- 01	G5 to K5
UF27 – WF27	3A9316-01	SP-5436	4A5576-01	G5 to K5
UR36, WR36, SR36	3A9520-01	SP-5438	4A5576-01	G5 to K5
UR48, WR48,	3A9520-01	SP-5437	4A5576-01	G5 to K5
SR48	3A9316-01	SP-5438	4A5576-01	G5 to K5
UF48, WF48	3A9313-01	SP-5435	4A5576-01	G5 to K5
UR60, WR60,	3A9316-01	SP-5434	4A5576-01	G5 to K5
SR60	3A9313-01	SP-5434	4A5576-01	G5 to K5
UF60, WF60	3A9313-01	SP-5435	4A5576-01	G5 to K5
UR72, WR72	3A9316-01	SP-5437	4A5576-01	G5 to K5
SR72	3A9313-01	SP-5434	4A5576-01	G5 to K5

Information is subject to change with units manufactured after K5 (3-6-2020) see parts manual.
[http://www.hoshizaki.com/docs/manuals/Steelheart UC WT PT pts.pdf](http://www.hoshizaki.com/docs/manuals/Steelheart_UC_WT_PT_pts.pdf)

If you have any questions, please contact the Technical Support Department at
tech-support@hoshizaki.com or 1-800-233-1940.