

## HOSHIZAKI AMERICA, INC. SERVICE BULLETIN

SB20-0017R1

Issued December 9, 2020 Revised January 13, 2021 Page 1 of 1

Subject: SA0103 Gear motor kit no longer available

Due to some internal components in this kit being no longer available, it is necessary that we no longer supply this gear motor kit.

For future orders it will be necessary to order the individual components, as called out in the specific models parts list. We will also be removing subs from our system that were previously directed to this kit.

Note: It is recommended that the capacitor and protector are replaced any time the gear motor is changed. See SB19-0004 for additional information related to the protector.

If you have question concerning this Service Bulletin, please contact the Technical Support Department at <u>tech-support@hoshizaki.com</u> or 1-800-233-1940.