



HOSHIZAKI AMERICA, INC.

SERVICE BULLETIN

SB25-0006

May 29, 2025

Page 1 of 1

Subject: IM-200 and IM-500 pump motor change

The water pump assembly has changed on the IM-200 and IM-500 series ice makers. In the future, if a water pump is needed for either of these units, please reference the table below.

Model number	Part name	Part number
IM-200BAA IM-200BAB IM-200BAC	Water Pump Assembly	2B0628A01
IM-500SAA IM-500SAB	Water Pump Assembly	SP-5727

If you have any questions concerning this change, please contact the Technical Support Department at tech-support@hoshizaki.com or 1-800-233-1940.