



HOSHIZAKI AMERICA, INC

SERVICE BULLETIN

SB26-0002

January 22, 2026

Page 1 of 1

Subject: Emblem 3B0043-XX substitution

The 3B0043-XX series of emblems are no longer available. As a result, all three versions of the 3B0043-XX emblem have been superseded by emblem part number **4A6943-01**.

While the 4A6943-01 emblem is not an exact match to the previous design, it is the emblem currently used in production

Please ensure that all servicing procedures adhere strictly to these guidelines to maintain compliance and ensure the safety and reliability of Hoshizaki products.

If you have any questions, please contact Hoshizaki Technical Support at:
1-800-233-1940, or at email: tech-support@hoshizaki.com